

How to Select the Correct Diaset Core Bit



If drilling conditions are unknown, start with a Matrix #7X, Heavy Duty (HD) crown design

Selection Guide & Troubleshooting Tips

A Define rock hardness

- 1. **For softer rock:** (MOH's hardness to 5). Use lower matrix numbers #2X #7X
- 2. For very soft rock (MOH's hardness to 3, use a PCD, Polycrystalline or Surface Set
- 3. Harder rock: Use higher matrix number #8X 13X

B Define the degree of abrasiveness, fractures or breaks within a particular rock formation

- 1. Coarse grained and fractured: use a lower matrix number
- 2. Fine grained and solid: use a higher matrix number

C Define type of diamond drill used:

- High powered drills (>100 h.p.), choose lower matrix numbers to maximize bit life.
- 2. **Low powered drills** choose a higher matrix number to get better penetration.
- 3. If ground or rig conditions force you to turn at lower RPM, then choose a lower matrix number. (Low RPM makes a matrix act differently)
- 4. Always use the highest RPM that suits the conditions.

Tips for selecting the correct matrix type

If you started with a Diaset matrix #7X HD, and if productivity is too slow, try a #8X or higher matrix number. A Turbo crown design will cut the fastest in hard, solid rock. If bit life is too low, try a lower matrix number, such as matrix #6X. Review the troubleshooting guide to pinpoint specific formation problems, to help you fine tune for the selection of the next bit.






Canada / U.S.A. Toll-free 1.800.663.5004



New Bit & Normal Wear Pattern



New Bit Observation


 v-ring pattern allows bit to start drilling quickly, stabilizes bit to bottom of hole.

Normal Wear

- O.D. and I.D. gauge intact
- flat to slight rounded profile
- "teardrop" matrix wear pattern behind diamond

Comments

- correct drilling procedure
- correct matrix selection







Canada / U.S.A. Toll-free 1.800.663.5004



I.D. Gauge Problems





Observations:

- rounded wear to I.D.
- excessive diamond exposure
- complete loss of I.D. gauge

Probable causes:

- Hard, broken or fractured formation
- excessive penetration rate for the RPM used
- insufficient fluid flow
- mis-latched innertube
- high bit load
- improper innertube adjustment

Possible solutions:


- retrieve innertube immediately upon core block
- clean hole properly before each core run
- use a harder (lower number) matrix
- increase pump output.
- check rod string for leaks, split rods
- adjust innertube to allow more fluid flow
- increase RPM



Canada / U.S.A. Toll-free 1.800.663.5004



O.D. Gauge Problems





Observations:

- rounded wear to O.D.
- complete loss of O.D. gauge

Probable causes:

- vibration
- excessive RPM
- bit reaming down an undersize hole
- bit following a worn bit
- insufficient fluid flow (attempting to make bit cut faster)

Possible solutions:

- alter RPM to reduce vibration. May have to change matrix to suit new RPM
- stabilize drill string
- adjust bit weight to reduce vibration
- check reaming shell, replace if undersized
- start drilling with new bit well before bottom of hole to ensure hole size matches new bit.
- increase fluid flow
- softer (higher number) matrix



Canada / U.S.A. Toll-free 1.800.663.5004



Burnt & Polished Bits



Burnt Bit Observations:

- melted crown.
- diamonds and waterways fused

Probable causes:

- insufficient fluid flow
- split drill rod(s)

Possible solutions:

- check pump
- check innertube adjustment
- check rods for leaks or cracks
- increase fluid flow

Polished Bit Observations:

- no or poor diamond exposure
- smooth surface

Probable causes:

- wrong matrix selection, diamond concentration too high
- drill too small to push this bit

Possible solutions:

- use a softer (higher number) matrix
- try decreasing fluid flow rate slightly
- sandblast face of bit to expose diamonds
- maintain torque, keep the bit cutting





Canada / U.S.A. Toll-free 1.800.663.5004